



Since 1968

HYTORC EDGE-30
PRESSURE/TORQUE CONVERSION CHART

PRESSURE IN PSI				PRESSURE IN BAR
	FT. LBS.	KGM	NM	
1500	4448	615	6030	104
1600	4744	656	6431	110
1800	5337	738	7235	124
2000	5930	820	8039	138
2200	6523	902	8843	152
2400	7116	984	9646	166
2600	7709	1066	10450	179
2800	8302	1148	11254	193
3000	8895	1230	12058	207
3200	9488	1312	12862	221
3400	10081	1394	13666	235
3600	10674	1476	14470	248
3800	11267	1558	15274	262
4000	11860	1640	16077	276
4200	12453	1722	16881	290
4400	13046	1804	17685	304
4600	13639	1886	18489	317
4800	14232	1968	19293	331
5000	14825	2050	20097	345
5200	15418	2132	20901	359
5400	16011	2214	21705	373
5600	16604	2296	22508	386
5800	17197	2378	23312	400
6000	17790	2460	24116	414
6200	18383	2542	24920	428
6400	18976	2624	25724	442
6600	19569	2706	26528	455
6800	20132	2784	27291	469
7000	20755	2870	28135	483
7200	21348	2952	28939	497
7400	21941	3034	29743	511
7600	22534	3116	30547	524
7800	23127	3198	31351	538
8000	23720	3280	32155	552
8200	24313	3362	32959	566
8400	24906	3444	33763	580
8600	25499	3527	34566	593
8800	26093	3609	35372	607
9000	26685	3691	36174	621
9200	27287	3774	36990	635
9400	27871	3855	37782	649
9600	28464	3937	38586	662
9800	29257	4046	39661	676
10000	29650	4101	40194	690

12420 TEXACO ROAD Houston, Texas 77013 713-453-6677 www.hyorctexas.com

This chart supercedes all prior version regarding this tool

08/02/2011