



Since 1968

HYTORC EDGE-4
PRESSURE/TORQUE CONVERSION CHART

| PRESSURE IN | | | | PRESSURE IN |
|-------------|----------|-----|------|-------------|
| PSI | FT. LBS. | KGM | NM | BAR |
| 1500 | 443 | 61 | 601 | 104 |
| 1600 | 474 | 66 | 643 | 110 |
| 1800 | 535 | 74 | 725 | 124 |
| 2000 | 596 | 82 | 808 | 138 |
| 2200 | 658 | 91 | 892 | 152 |
| 2400 | 720 | 100 | 976 | 166 |
| 2600 | 782 | 108 | 1060 | 179 |
| 2800 | 844 | 117 | 1144 | 193 |
| 3000 | 906 | 125 | 1229 | 207 |
| 3200 | 969 | 134 | 1314 | 221 |
| 3400 | 1032 | 143 | 1399 | 235 |
| 3600 | 1094 | 151 | 1483 | 248 |
| 3800 | 1157 | 160 | 1569 | 262 |
| 4000 | 1220 | 169 | 1654 | 276 |
| 4200 | 1283 | 177 | 1740 | 290 |
| 4400 | 1347 | 186 | 1827 | 304 |
| 4600 | 1410 | 195 | 1912 | 317 |
| 4800 | 1474 | 204 | 1999 | 331 |
| 5000 | 1537 | 213 | 2084 | 345 |
| 5200 | 1599 | 221 | 2168 | 359 |
| 5400 | 1662 | 230 | 2254 | 373 |
| 5600 | 1724 | 238 | 2338 | 386 |
| 5800 | 1787 | 247 | 2423 | 400 |
| 6000 | 1849 | 256 | 2507 | 414 |
| 6200 | 1911 | 264 | 2591 | 428 |
| 6400 | 1974 | 273 | 2677 | 442 |
| 6600 | 2036 | 282 | 2761 | 455 |
| 6800 | 2099 | 290 | 2846 | 469 |
| 7000 | 2161 | 299 | 2930 | 483 |
| 7200 | 2223 | 307 | 3014 | 497 |
| 7400 | 2285 | 316 | 3098 | 511 |
| 7600 | 2346 | 324 | 3181 | 524 |
| 7800 | 2408 | 333 | 3265 | 538 |
| 8000 | 2470 | 342 | 3349 | 552 |
| 8200 | 2531 | 350 | 3432 | 566 |
| 8400 | 2593 | 359 | 3516 | 580 |
| 8600 | 2654 | 367 | 3599 | 593 |
| 8800 | 2716 | 376 | 3683 | 607 |
| 9000 | 2777 | 384 | 3766 | 621 |
| 9200 | 2837 | 392 | 3847 | 635 |
| 9400 | 2898 | 401 | 3930 | 649 |
| 9600 | 2958 | 409 | 4011 | 662 |
| 9800 | 3019 | 418 | 4094 | 676 |
| 10000 | 3079 | 426 | 4175 | 690 |

12420 TEXACO ROAD Houston, Texas 77013

713-453-6677

www.hyorctexas.com

This chart supercedes all prior version regarding this tool

08/02/2011